


Sheet 1, Side B DP-169-01 1st printing



#1 CC34

- 2. SA Harness Assembly:
- Atari part number A036836-01. You can make one of these yourself. The following is an illustration of its construction.
- 3. Two jumper wires with "hook" connectors on each end.

### B. Signature Analysis Setup Procedure

- 1. Connect Signature Analyzer to the matching pins of SA connector on the SA Harness assembly. In other words, GND should match up with GND, etc.
- 2. Set Self-Test Switch of Red Baron™ game to ON. After approximately three seconds, the TV monitor should display the selftest pattern.

## C. Signature Analysis Test #1 Procedure

- 1. Plug SA Harness Assembly Test #1 connector onto Signal Analyzer header on Auxiliary PCB (the black wire on the connector should be at the top).
- 2. Connect a jumper between PWR ON RESET test point and ground. This places a continuous RESET to the microprocessor on the Analog Vector-Generator PCB.
- 3. Set Signature Analyzer START to \_\_/\_, STOP to \_\_/\_, and CLOCK to\_/ .
- 4. Connect a jumper wire between the PU test point on the Auxiliary PCB and the tip of the Signature Analyzer probe.
- 5. The Signature Analyzer should indicate CC34.
- 6. Probe for signatures as shown in Figure 1 to the left. If all signatures are correct, continue with D. Signature Analysis Test #2A Procedure. If incorrect, refer to G. Isolating a Failing Circuit.

# D. Signature Analysis Test #2A Procedure

- 1. Remove the jumper wire from Signature Analyzer probe.
- 2. Plug SA Harness Assembly Test #2 connector onto Signature Analyzer header on Auxiliary PCB.
- 3. Remove jumper from PWR ON RESET on the Analog Vector-
- 4. Set Signature Analyzer START to \_\_/\_, STOP to \_\_\_\_, and
- 5. Connect one end of the jumper wire to the ground test point on the Analog Vector-Generator PCB. Touch the DIAG 'STEP' test pad with the other end of the jumper wire five times. After the
- 6. Verify that setup procedure is correct by probing +5V for a signature of 3951.
- 7. Probe for signatures as shown in Figure #2A to the left. If all signatures are correct, continue with E. Signature Analysis Test #2B Procedure. If a signature is incorrect, refer to G. Isolating a Failing Circuit.

# E. Signature Analysis Test #2B Procedure

- 1. Make sure the SA Harness Assembly Test #2 connector is plugged onto Signature Analyzer header on Auxiliary PCB.
- 2. Make sure jumper wire is removed from the PWR ON RESET test point on the Analog Vector-Generator PCB.
- 3. Set Signature Analyzer START to \_/\_, STOP to \_\_\_, and
- 4. Verify that setup procedure was correct by probing +5V for a signature of 3951. If not 3951, press the reset button the the Analog Vector-Generator PCB, return to D. Signature Analysis Test 2A Procedure and once again do step 5. Then return to this
- 5. Probe for signatures as shown in Figure #2B to the left. If all signatures are correct, continue with F. Signature Analysis Test #3 Procedure. If a signature is incorrect, refer to G. Isolating a Failing Circuit.

#### F. Signature Analysis Test #3 Procedure

#3 3951

#2 3951

- 1. Plug SA Harness Assembly Test #3 connector onto Signature Analyzer header on Auxiliary PCB.
- 2. Make sure jumper wire is removed from PWR ON RESET on the Analog Vector-Generator PCB.
- 3. Set Signature Analyzer START to \_/ , STOP to \_\_ , and CLOCK to\_/\_.

Generator PCB, return to D. Signature Analysis Test 2A Pro-

- Verify that setup procedure was correct by probing +5V for 3951. If not 3951, press the reset button on the Analog Vector-
- 5. Probe for signatures as shown in Figure #3 to the left. If all signatures are correct, then Math Box Circuitry of Analog Vector-Generator PCB is OK.

cedure and once again do step 5. Then return to this step.

## G. Isolating a Failing Circuit

If one of the 137004-001 chips C/D2, E2, F/H2, or J2 has a bad signature, there is a chance it will cause the other 137004-001 chips to have bad signatures also. If this is the case, make sure all input signatures (A0-A19, EDB0-EDB7 and CLK) are correct. If they are correct, replace the 137004-001 chips. If replacing the 137004-001 chips doesn't fix the problem, check for shorted or open traces in the area of the 137004-001 circuitry.

If you find an incorrect signature, find the signature test point of the Math Box Circuitry on Sheet 3, Side B. Locate the IC from which the signature is being output. Check all inputs of that IC.

If all input signatures are correct: Remove the Auxiliary PCB from the circuit. Check the circuit traces common to the failing IC pin on both the top and bottom of the PCB for shorts to another circuit trace. If the circuit traces are not shorted, then replace the failing IC.

If an input signature is incorrect: Locate on the schematic the IC source of the failing signature. Check the input signatures of that IC. If all input signatures are correct, then that is the failing IC. If this IC has a failing input signature, then continue "upstream" in the circuit flow until the failing IC is isolated.



Sheet 1, Side B

**RED BARON™** 

**Auxiliary PCB Signature Analysis Procedure** Section of 036305-01 A

© 1981 Atari, Inc.

NOTICE TO ALL PERSONS RECEIVING THIS DRAWING CONFIDENTIAL: Reproduction forbidden without the specific written permission of Atari, Inc., Sunnyvale, CA. This drawing is only conditionally issued, and neither receipt nor possession thereof confers or transfers any right in, or license to use, the subject matter of the drawing or any design or technical information shown thereon, nor any right to reproduce this drawing or any part thereof. Except for manufacture by vendors of Atari, Inc., and for manufacture under the corporation's written license, no right to reproduce this drawing is granted or the subject matter thereof unless by written agreement with or written permission from the corporation.

W A Warner Communications Company